

- Range 1
 - Cont./- Clearing Sand from rear of R1 Shelter
 - Repair IPSC Frames (90x40 Timber)
 - Service Pistol Frames – Replace as needed (50x25 Timber)
 - Fit New Door Latch/Lock

- Range 2
 - Add/Replace “.22Rimefire Only” Signs.
 - Bolt/Bracket Rear Wall to concrete
 - Fit New Door Latch/Lock

- Ranges 3 & 4
 - Repair IPSC Frames (90x40 Timber)
 - Repair Baracades (replace Plywood)

- Range 5
 - Replace Rubber Hose Bump stops on Falling Plate Frames
 - Add Rubber Sheet backdrop/overhang from rear edge of Falling plate Roof
 - Extend R5 Roof to rear wall

- ALL Ranges
 - General sweep up / tidy up / weed etc.
 - Collect/remove all spent cases
 - Fit Rubber Backing to ALL Steel Targets Inc. those in the Containers
 - Fit New Flag on Hill @ R1. Replace cord and ensure “BOTH” cords pass thru tube

- Hill behind Ranges
 - Tree/Flax planting on hill and end of each Range

- Club Rooms
 - Sweep and general tidy up of Club Rooms
 - Replace Corrugated Roofing on front Veranda

- Carpark
 - Spread Gap20 on inside fenced area
 - Put only green matting into Skip Bin
 - Burn pile of OLD Timber at rear of Carpark

Materials Ordered/Required:

- 1.5T Excavator/Digger(s)
- Battery Grinders with Wire Wheel to clean back pf Steel targets prior to gluing rubber
- 8m3 Gap 20 Metal - (*Ordered and already Delivered*)
- 100x25 RS (Range 1 Service Pistol Frames)
- 90x40 framing timber for ISPC Frames (Ranges 1,3&4)

Tools required:

Ladders, Wheel Barrows, Buckets, Hand Carts, Trailer, Battery Tools, Saw/Hammer/Nails / Battery Tools, Shovels etc.

And anything else anyone is aware of that needs repairing